


Use a metal measuring tape (cloth tapes may stretch).



Inside Mount:


Blinds are mounted inside the window casing.

WIDTH

- Measure in 3 places to the nearest 1/8"
- Order using the **shortest** measurement

HEIGHT

- Measure in 3 places to the nearest 1/8"
- Order using the **longest** measurement



Outside Mount:

Blinds are mounted outside the window casing.

WIDTH & HEIGHT

- Measure the exact width and height of the area to be covered
- Add 4" to both width and height for better light and privacy control